


**Tilcon New Jersey
Riverdale Quarry
Quarterly Blast Compliance Summary
January through March 2021**

Date	Time	Recording Location	Within NJ Ground Vibration Limits*	Within NJ Air Overpressure Limits**
1/4/2021	12:00	211 Hamburg Turnpike	Yes	Yes
1/4/2021	12:00	Cablevision Tower	Yes	Yes
1/4/2021	12:00	Bloomingtondale DPW Yard	Yes	Yes
3/1/2021	12:45	211 Hamburg Turnpike	Yes	Yes
3/1/2021	12:45	Cablevision Tower	Yes	Yes
3/1/2021	12:45	Bloomingtondale DPW Yard	Yes	Yes
3/8/2021	10:45	211 Hamburg Turnpike	Yes	Yes
3/8/2021	10:45	Cablevision Tower	Yes	Yes
3/8/2021	10:45	Bloomingtondale DPW Yard	Yes	Yes
3/10/2021	11:30	211 Hamburg Turnpike	Yes	Yes
3/10/2021	11:30	Cablevision Tower	Yes	Yes
3/10/2021	11:30	Bloomingtondale DPW Yard	Yes	Yes
3/17/2021	13:30	211 Hamburg Turnpike	Yes	Yes
3/17/2021	13:30	Cablevision Tower	Yes	Yes
3/17/2021	13:30	Bloomingtondale DPW Yard	Yes	Yes
3/23/2021	12:00	211 Hamburg Turnpike	Yes	Yes
3/23/2021	12:00	Cablevision Tower	Yes	Yes
3/23/2021	12:00	Bloomingtondale DPW Yard	Yes	Yes
3/30/2021	14:45	211 Hamburg Turnpike	Yes	Yes
3/30/2021	14:45	Cablevision Tower	Yes	Yes
3/30/2021	14:45	Bloomingtondale DPW Yard	Yes	Yes


*State of New Jersey Administrative Code Title 12:190; Subchapter 7.26
**State of New Jersey Administrative Code Title 12:190; Subchapter 7.25

Comparison of Measured Blast Vibrations to Current U.S. Bureau of Mines Recommendations Tilcon New Jersey Pompton Lakes 1st Quarter 2021



*As per State of New Jersey Administrative Code 12:190; Subchapter 7.26

Air Overpressure Levels from Tilcon New Jersey - Pompton Lakes Quarry 1st Quarter 2021



*As per State of New Jersey Administrative Code Title 12.190; Subchapter 7.25

■ 211 Hamburg Turnpike
 ■ Cablevision Tower
 ■ Bloomingdale DPW Yard